



Basic and Advanced Welding Supply List

Required Materials You Must Have to Start the Class

1. Welding Hood (Standard or Electronic) With Flip-Up #10 or #11 Lens
2. Welding Gloves (Heavy Duty, Full Gauntlet)
3. Chipping Hammer
4. Cutting Goggles With (Flip-Up) #4 Lens
5. Wire Brush
6. Leather Coat (Optional)
7. Safety Glasses
8. Striker
9. Wire Cutters (Side Cutters)
10. Boots

Students Taking TIG (Advanced Welding) You Will Also Need:

1. Lincoln Electric KP508 - Parts Kit for PTA-17, 17V